BRUHAT BANGALORE MAHANGARA PALIKE		
Inspection Report		
1	Name Of Work:	Providing and laying HDPE water line in Brindavana nagara Block 2 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2263/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/310/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,97,000/-
5	Job Code No.	017-14-000031
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/230/13-14 Dtd: 07.02.2014
8	Work order Number & Date	EE/RRND/WO/230/13-14 Dtd: 07.02.2014
9	Contract Amount as per Agreement	Rs. 53,46,219/-
10	Bill Amount	Rs. 41,67,175=92
11	B.R No. & Date	248/14-15 Dtd: 30.06.2014
12	Agency	K Shivakumar
13	M.B. Number & Page No. of Measurement records	119/13-14 Page No 11877 to 11883
14	Date of Inspection	04.09.2017
15	Enclosures	4 Number of photos taken during inspection
16	I have Inspected the above Location along with the Concerned person, as per EE (RRND) Letter No EE/RRN/PR/414/A/17-18 Dated 1-9-2017. It is observed that most of the Items indicated in the Xerox Copy of MB/XL sheets are not susceptible for Inspection Report measurements, as the nature of work is Laying HDPE water Line, as such the photos taken during the execution of work have been scrutinised and Inspected, it appears that the above work has been done. The Items which are susceptible for measurements have been Checked and found to be satisfactory. This has a reference to the NOC Issued by Lokayukta Vide Letter No LOK/INV(I)/CT/Crim 60/2017 dated 1-8-2017	

4/9/2017
(R. Sathyanarayana)
Inspecting Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

EE (RRN) Division, RR Nagara Zone.

Scanned by CamScanner